



Fig.1 Main facade of Mr. Buenano's shop



Fig.2 : Asbestos cement roofing of the shop



Fig.3 : Single pane windows with iron gratings




Fig. 4 : Fluorescent tube lamp used in the shop



Fig. 5 : Ceiling fan in the shop 75 W



Fig. 6 : Refrigerator of the shop



Fig. 7 : Freezer 1 of the shop



Fig. 8 : Freezer 2 of the shop



Fig. 9 Water buster pump of the shop